

ABSTRACT

A method of manufacturing an optoelectronic packaging comprises placing a solder preform between a metal cover and an insulating base, applying pressure to the metal cover and the insulating base, and applying a current through multiple conductive vias to heat the solder preform to melt.